

Olympic Park Railway Station

Track record 1998

Location of project

Sydney, Australia

Products/system used

Interzinc[®] 315, Intercure[®] 420, Interfine[®] 630

Project owner

Olympic Coordination Authority

Contractor

Leighton Contractors

ISO12944 environment

C3

